CIVIL QUALITY CONSULTANTS & ENGINEERS
ISO 9001:2015 Certified & NABL Accredited Laboratory as per ISO/IEC - 17025-2017

Testing of Construction Material - Mechanical, Soil, Bitumen, Non Destructive Testing Services, Project Management Consultants, Third Party Quality Assurance, DPR.

Name of Work : Providing Rain Water Harvesting in selected area of Jalahalli in ward no 16 Jalahalli, BBMP, Bangalore.

Name of Client	:	**Executive Engineer,** RR Nagara Division, BBMP, Bangalore.
Contractor/Agency	:	**Sri. T Chandrasekar Reddy,** Contractor, Bangalore.
Total Cost	:	Rs. 26.46 Lakhs
Date of Inspection	:	20.02.2021
Status of Bill	:	1st and final Bill
In the Presence of	:	(a) **Assistant Engineer (W. No.16),** BBMP, Bangalore.
	:	(b) **Mr. Mohan G,** Engineer M/S Civil Quality Consultants and Engineers, Bangalore

Sl. N	Description of the Item		Unit	Qty	Comments / observations
1	Earthwork excavation by manual means for foundation of buildings, water supply and	:	Cum	1004	Work done up to the billed quantity and Quality is satisfactory
2	Providing Nominal 100mm size stone aggrigates (Page no I, SI NO.23)Code NO.0175	:	Cum	251.1	Work done up to the billed quantity and Quality is satisfactory
3	Providing Nominal 40mm size stone aggrigates	:	Cum	251.1	Work done up to the billed quantity and Quality is
4	Providing Nominal 20mm size stone aggrigates	:	Cum	251.1	Work done up to the billed quantity and Quality is
5	Providing And filling sand in foundation to required deapth for subsoilo treatment	:	Cum	251.1	Work done up to the billed quantity and Quality is satisfactory
6	Providing And fixing ms grill work for windows and ventilators using ms flats or ms	:	Kg	7000	Work done up to the billed quantity and Quality is satisfactory

CIVIL QUALITY CONSULTANTS & ENGINEERS ★ Bangalore

Corporate Off.: No. 133, Bhuvaneshwarinagar, Doddabasti Main Road, Bangalore-560 056.
Contact: 8553518550, 080-23240644 Email: civilqualityconsultants@gmail.com

Scanned with CamScanner